: REPLACEMENT WINDOW ASSEMBLY

User:

Thursday, 18/09/2008 11:41:24 AM

Linda Lacelle

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number**

: 42121 -: 11174

P.O. Number

: 18/09/2008 This Issue Prsht Rev.

First Issue

: NC : 11

: 42024

Type

S.O. No. :

: SMALL /MED FAB

Previous Run

Checked & Approved By

Comment

Written By

: Est. B 05.05.25

Added Step 11 KJ/JLM Est. C 06.05.09 Ecn 798

Est Rev:D Now on Wateriet 06-06-16 JLM

Est rev E rev C dwg

07.09.28 EC verified by: DD

Drawing Name

: D3290041 Part Number D3290 REV C **Drawing Number**

Project Number : N/A : C

Drawing Revision Material

Due Date : 25/09/2008

Split 5

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0 M6061T6S040



Comment: Qty.:

3.9375 sf(s)/Unit Total: 47.2500 sf(s)

M6061T6S040

Batch: 109396

2.0 WATER JET FLOW WATER JET

6061-T6 .040 Sheet



Comment: FLOW WATER JET

1-Cut aş per Dwg D3290 (use prog. for D3290-1)

Dwg Rev: C Prog Rev:____

P6-P-8 EN



2-Deburr if necessary

3.0



P6-P-8 F1



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

SECOND CHECK



Comment: SECOND CHE

5.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1



08-12-6

Process Sheet Customer: CU-DAR001 Dart Helicopters Services Drawing Name: REPLACEMENT WINDOW ASSEMBLY Job Number: 42121 Part Number: D3290041 Job Number: Seq. #: Machine Or Operation: Description: 6.0 POWDER COATING POWDER COATING Comment: POWDER COATING Powder Coat White Gloss (Ref. 4.3.5.1) as per QSI 005 4.3 START TIME: OVEN TEMPERATURE: FINISH TIME: QC3 7.0 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 08.16 D2126 8.0 Comment: Qty.: Total: 78.0000 f(s) Locking Seal Pick: Qty Part Number Description D2126-0780 Locking Seal 9.0 D32903 Comment: Qty.: 1.0000 Each(s)/Unit Total: 12.0000 Each(s) Window Pick: Qty Part Number Description Batch D3290-3 Window 10.0 SMALL FAB 1 SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 Assemble as per Dwg D3290 Clean D3290-041 and place in plastic wrap • 11.0 QC5 INSPECT WORK TO CURRENT STEF

Comment: INSPECT WORK TO CURRENT STEP

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: REPLACEMENT WINDOW ASSEMBLY

Job Number: 42121

Part Number: D3290041

Job Number:



Seq. #:

12.0

Machine Or Operation:

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

FINAL INSPECTION/W/O RELEASE



08/11/7 & 08/12 104 H

13.0 QC21

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



le 8/1204

DART AEROSPACE LTD	Work Order:	42121
DESCRIPTION: REPLACEMENT WINDOW ASS'Y	Part Number:	D390-04
Inspection Dwg: D3290 - 1, Rev:		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article X Prototype

Drawing Dimension Tolerance		Actual Dimension	Accept	Rejest	Method of Inspection	Comments	
		417	*				
d 1357	4.066001	.757	*	12 13			
29.00	14- :030	29.00	×				
18.50	4030	18.50	×		7.94		
01.01	1030	10.10	>6				
14.00	T030	14,00	×	•			
13.61	4 .030	1365	×				
1.50	14 .030	1,513	×			1	
1.11	4 030	1,094	XP				
		***			9		
				e e	9	3 1	
		I Tale		, a		- VA	
						Mal.	
						3.70	
					-		
				2		3.43	
	*				1	Hy & J.	
					e de	744	
- X 5		71			EDA.		
		SI SI			1. 15.02		
						THE PARTY	
7 28 3	B-T	. 4					

Measured by: B Audited by: Prototype Approval: N

Date: 9-9-H Date: 08/10/0 Date: 19

Rev	Date	Change	 11		Revised by	Approved
A		New Issue	70	D3290-041	KJ/JLM	





